



U =

1.0e-006 *

0.0000
0.0000
-0.0000
0.1827
0.0938
-0.2754
0.4764
0.0030
-0.2090
0.0949
-0.0030
0.2120
0.1037
-0.0938
-0.1307
0.0000
-0.0000
-0.0000

FBC =

-53.9474
-9.3845
54.5183
0.0000
0.0000
-0.0000
100.0000
0.0000
-0.0000
0.0000
0.0000
100.0000
0.0000
0.0000
-0.0000
-46.0526
9.3845
36.0972

F_e =

-53.9474	-61.8421	38.1579	38.1579	46.0526	7.8947
-9.3845	9.0817	9.0817	9.0817	-9.3845	-18.4662
54.5183	24.2777	-37.5644	53.3539	9.9554	-23.7068
53.9474	61.8421	-38.1579	-38.1579	-46.0526	-7.8947
9.3845	-9.0817	-9.0817	-9.0817	9.3845	18.4662
-0.5709	37.5644	46.6461	-15.1960	36.0972	5.2406